

1969 Chevrolet Corvette Coupe C3

Documented improvements made to vehicle since 1985

VIN: 1943795714476

Shop Rate: \$ 85.00Assigned Mechanics:
Juan Montoya
N M Apostol

WORK DESCRIPTION	Labor	Hour	Cost
1. New Paint - ca. 1985			\$ 2,800.00
2. New Engine - 2006			\$ 7,200.00
3. New Carburetor - 2008			\$ 4,567.26
4. New fuel pump - 2008			\$ 416.67
5. New air cleaner - 2008			\$ 370.00
6. New exhaust system - 2008			\$ 1,675.00
7. Left dr. (SUB-CONTRACT Dangerous Curves)			\$ 1,036.00
Total Labor and Parts Outsourced			\$ 18,064.93
8. New fuel line (supply and return) - 2010	8	\$	680.00
9. New rear brake hydraulic line - 2010	2.5	\$	212.50
10. New horn contact and steering wheel assembly - 2010	14	\$	1,190.00
11. New vacuum system hoses for headlights and windshield wiper door systems - 2010	8	\$	680.00
12. New rear suspension, brake assembly, trailing arms, rear struts, calipers, disk brake pads, shock ab	18	\$	1,530.00
13. New rear wiring harness incl. fiber optics - 2010	16	\$	1,360.00
14. New windshield wiper motor and washer pump assembly - 2010.	3	\$	255.00
15. New windshield washer hoses - 2010	3	\$	255.00
16. Restore speedometer - 2010	2.5	\$	212.50
17. New oil pressure gauge - 2010	2	\$	170.00
18. New electric clock - 2010	2	\$	170.00
19. New battery - 2010	1	\$	85.00
20. New handbrake cables - 2010	4.5	\$	382.50
21. New headlight washer nozzles - 2010	1.5	\$	127.50
22. Replace wiper arms and blades - 2010	3.5	\$	297.50
23. Replace all vacuum system relays, switches and by-pass controls - 2010	14.5	\$	1,232.50
24. Replace left and right sight courtesy light switch - 2010	2.5	\$	212.50
25. Replace left and right door ajar switches - 2010	3.5	\$	297.50
26. Replace luggage compartment courtesy light - 2010	1.5	\$	127.50
27. Restore rear storage compartment lds - 2010	5.5	\$	467.50
28. Replace rear right storage compartment opening latch assembly- 2010	1.5	\$	127.50
29. Replace center storage compartment light and lens - 2010	1	\$	85.00
30. Replace rear anti-theft alarm activation lock, wiring, horn, hood relay - 2010	7.5	\$	637.50
31. Replace rear license plate light fixture - 2010	2	\$	170.00
32. Replace seat upper and lower rubber supports - 2010	1	\$	85.00
33. New interior instrument lamp bulbs (12) - 2010	2.5	\$	212.50
34. Restore anti-theft wiring harness, relays, flasher, horn and engine compartment trip switch - 2010	7.5	\$	637.50
35. Install new dashboard wiring harness - 2010	14	\$	1,190.00
36. Install new trunk compartment light fixture - 2010	2	\$	170.00
37. Install new headlight door operation alarm switch (right side) - 2010	2	\$	170.00
38. Install new 4 speed shifter upper boot - 2010	2	\$	170.00
39. Install (2) new radio speakers - 2010	2	\$	170.00
Total In-House Labor	162	\$	13,770.00

SUPPLIER		Cost
Advanced Auto Parts	mount	\$ 82.20
Advanced Auto Parts	horn,alarm	\$ 17.03
bennett auto supply	courtesy switch	\$ 6.17
Crown Car	manual, lights, carb,jets,horn button	\$ 651.14
Crown Car	fuel hose, exhaust gasket,battery cable repair	\$ 388.44
Crown Car	12v battery	\$ 110.71
Dr. Rebuild	wiring guide	\$ 40.45
Dr. Rebuild	vacuum hose kit-headlamps	\$ 76.45
Dr. Rebuild	vacuum system guide	\$ 35.45
Dr. Rebuild	cigarette lighter shield, storage lock, retainer etc	\$ 80.40
Ecklers	cable, bumpers, etc	\$ 341.66
Ecklers	backup light switch rod w/clips	\$ 21.23
Ecklers	backup light switch, cam turn cancel	\$ 194.75
Ecklers	door ajar switch, compartment lens, license plate light assy.	\$ 139.92
Ecklers	Front hood bolts, bushings, cable	\$ 44.57
Ecklers	line, oil pressure, gauge, anti-theft switch,loops	\$ 162.31
Ecklers	Courtesy light socket	\$ 18.09
Ecklers	shift boot, clock,support	\$ 250.99
FEDEX	SHIP SPEEDOMETER	\$ 56.95
Fedex	shipping charge speedometer	\$ 56.95
FEDEX	SHIP CORES FOR REAR SUSPENSION	\$ 67.73
Harbor Freight	Jacks	\$ 63.88
harbor freight	jack stands	\$ 63.88
Home Depot	saw blades	\$ 16.79
Home Depot	9" cutting blades	\$ 8.29
Home Depot	9" cutting blades	\$ 8.50
lectric limited	tool	\$ 30.00
lectric limited	dash harness	\$ 588.70
lectric limited	neutral safety switch	\$ 71.23
lowes	misc1. Hardware	\$ 22.57
NAPA	filter,oil,sparkplug	\$ 101.28
NAPA	wiper blade	\$ 14.89
NAPA	brakeline	\$ 36.18
NAPA	bulbs	\$ 16.44
NAPA	fuses	\$ 7.16
NAPA	clamp	\$ 2.86
NAPA	switch	\$ 3.18
NAPA	fuses, relay	\$ 37.83
NAPA	torque, adapter	\$ 52.89
NAPA	terminal sleeves	\$ 24.57
NAPA	brake fluid, line, undercoating (1)	\$ 42.76
NAPA	fuel line	\$ 18.08
Ripper Welding	wiper blade repair	\$ 43.00
shell	gasoline	\$ 44.46
speedometer plus	speedometer rebuild	\$ 178.00
suburban chevrolet	contact switch	\$ 4.31
ZIP	rear suspension/vacuum parts	\$ 2,194.83
ZIP	manuals,dome lens,headlamp washer hoses	\$ 89.01
ZIP	washer nozzles	\$ 45.34
ZIP	rear wiring harness	\$ 255.00
ZIP	shipping charge	\$ 91.10
ZIP	windshield washer pump	\$ 74.95
ZIP	windshield wiper motor	\$ 150.95
ZIP	rear storage latch	\$ 14.73
ZIP	horn contact	\$ 7.00
ZIP	alarm switch w/keys,speakers	\$ 91.25
ZIP	windshield washer pump anti drip solenoid	\$ 218.95
	Total Parts	0 \$ 7,578.43

Total In-House Parts and Labor \$ 21,348.43**Total All Parts and Labor \$ 39,413.36**